



Source: John Milner Associates, Inc.

Photo 15: Typical view of the vegetative character of the woodland area. (50\_Spindle-woods)



Source: John Milner Associates, Inc.

Photo 16: Japanese stilt grass (*Microstegium vimineum*) is an invasive grass that was observed in the Jamesson cemetery. (12\_MG\_cemetery-microsteg)





Source: John Milner Associates, Inc.

Photo 17: The Mount Gilead entrance drive terminates in a circle near the north façade of the house. (JMA\_10)



Source: John Milner Associates, Inc.

Photo 18: The west façade of the Colonial Revival garage stands near the Mount Gilead House. (B\_447\_MG\_stables)





Source: Fairfax County Park Authority.

Photo 19: Fairfax County stabilized the Mount Gilead garage during the late summer/early fall 2005, as shown in this photograph of the building's main façade.



Source: Fairfax County Park Authority.

Photo 20: View of the stabilization efforts from the rear of the garage.





Source: John Milner Associates, Inc.

Photo 21: One of two Colonial Revival outbuildings, known as the summerhouses, that sit behind the Mount Gilead House. (B\_448\_MG\_outbldg)



Source: John Milner Associates, Inc.

Photo 22: The southeastern façade of the Spindle House, originally built from a Sears kit. (B\_490\_MG\_poss\_SearsHs)





Source: Fairfax County Park Authority.

Photo 23: The remains of the Sedinger House, which collapsed in late summer 2005.



Source: John Milner Associates, Inc.

Photo 24: One of the two white-washed stone pillars, and the associated iron gate found at the entrance to the Mount Gilead House property. (JMA\_02)





Source: John Milner Associates, Inc.

Photo 25: An interpretive sign located along Mount Gilead Road. (JMA\_03)



Source: John Milner Associates, Inc.

Photo 26: A white picket fence edges the rear of the Mount Gilead House precinct. (33\_Mt-Gilead-picket)





Source: John Milner Associates, Inc.

Photo 35: An aluminum gate restricts access between the Spindle House area and the Mount Gilead House precinct. (38\_Spindle\_Gate1)



Source: John Milner Associates, Inc.

Photo 36: Remnants of a wooden picket fence near the Spindle House. (49\_Spindle-fence)





Source: John Milner Associates, Inc.

Photo 37: Ornamental wire fence near the Spindle House property. (JMA\_23)